



國家同步輻射研究中心
National Synchrotron Radiation Research Center

Post-mortem diagnostics for the Taiwan Light Source

K.H. Hu, Jenny Chen, C.Y. Wu, Demi Lee, C.H. Kuo, P.C. Chiu,
S.Y. Hsu, C.J. Wang, K.T. Hsu, M.S. Yeh, Ch. Wang

Presented by K.T. Hsu

NSRRC, Hsinchu 30076, Taiwan

NSRRC






- NSRRC accelerator facility

Taiwan Light Source (TLS) and Taiwan Photon Source (TPS)

- Operation status of the TLS (**poster WEPC058**)
- Tools to capture data for post-mortem analysis
- Some trip scenarios analysis
- Summary



NSRRC accelerator facility



(Courtesy of Google Earth)



NSRRC accelerator facility - cont.

國家同步輻射研究中心

Taiwan Light Source

Hsinchu Science Park

Taiwan
Photon
Source

Tsing-Hua University

Chiao-Tung University

- 中心設施
鄰近單位
- 1 大門
 - 2 行政大樓
 - 3 研光大樓
 - 4 儀光大樓
 - 5 增能環館
 - 6 儲存環館
 - 7 機電館
 - 8 招待所
 - 9 國家高速網路與計算中心
 - 10 交通大學



Taiwan Photon Source project

Aerial view

Activity center &
guest house &
Utility building no.3

TPS office

**Taiwan Photon Source
(TPS)**

3 GeV, C=518.4 m

Commissioning : 2013⁺

**TPS
related
poster:**

TUPC054

TUPC120

TUPC127

TUPD007

TUPP025

WEPC004

WEPC005

WEPC006

WEPC017

WEPC082

WEPC104

WEPC113

WEPC114

WEPC142

THPC005

THPC041

THPC120

THPP118

THPP143₅

**Taiwan Light Source
(TLS)**


1.5 GeV, C=120 m

Dedication in 1993

North



TLS beamline status



ID Status

IDs:

W20

U5

U9

EPU5.6

EPU4.6 (2009)

Superconducting IDs:


SWLS

SW6

IASW6-R6

IASW6-R2 (2009)

IASW6-R4 (2009)




(*) : Participating Research Group



TLS operation status

- 301 mA Top-Up operation
- ~ 0.05% photon flux constancy were achieved routinely
- > 98 % availability achieved




- Keeping high stability and high availability is our commitment to the users
- How to achieve this?



Bad experience - one of an example

Problem of master oscillator related problem



Bad experience - one of an example - cont.

Trilogy of the abnormal high trip rate in (February - December, 2000)


Power distribution panel,
bad contact
(Voltage drop to about 70 ~80 V
in a few power line cycle)

Control board malfunction ,
(always in by-pass mode,
no indication)

Output coaxial switch
was open when line
voltage dropped to less
than 90 V



If some trip diagnostic tools existed,
it might be solved soon!



RF Loss
(< 0.1 sec)

Beam Trip



DORIS CAVITY

Rule of Thumb : Don't Trust "Common Sense"



Proverb

久病成良醫 (三折肱成良醫)

Failure is the Mother of Success (失敗是成功之母)

Experience is the Mother of Wisdom (經驗是智慧之母)

Fall into a moat and you will gain wisdom from the experience (吃一塹長一智)

Fall Down Seven Times, Get Up Eight (七轉八起)

Success comes from experience; but **experience comes from failure** (Mark Twain)

Strategies to improve or to keep high availability

Preventative maintenance

Identify weaknesses of the system and remove them

Operation automation

Analyze each trip event to identify where is the problem

=> Fault diagnostic


Capture data before and after specific event happened

=> Post-mortem analysis

Many measures were done after identify the real reasons for further improvement!




Various tools for beam trip data acquisition




➤ All tools are triggered by the sum signal:

beam trip + superconducting IDs quench + SRF trip + predefined trigger conditions

How to detect beam loss?



Superconducting insertion device quench detection





Recorder, oscilloscope, and b-by-b feedback processor, t-by-t BPM

Recorder



Oscilloscope




Data memory in bunch-by-bunch feedback processor




Post-mortem buffer of BPM electronics








VME based fast digitizer






VME based fast digitizer - cont.




➤ Live display for every top-up injection cycle

➤ Store data if beam loss occurred





Linac klystron stand arcing diagnostics



This symptom is just the precursor of isolation breakdown!






Diagnostic tools for the SRF system

- Try to understand the reasons of every RF/SRF fault
- **What we experience a lot...**
 - SRF “quench” due to fast change of beam behaviors...
 - Fast beam dump or partial beam loss due to various reasons;
 - Fast beam dump due to kicker misfired;
 - Orbit change;
 - ...
 - LLRF’s feedback loop becomes unstable due to heavy beam loading...
 - False alarm by window arcing...
 - We experience with a “new” kind of trip event every few months and usually solve it by reducing various feedback loop gains.
 - Modified many LLRF electronics to avoid false alarm.
- **What we never or seldom experience...**
 - Multipacting in the cold surface waveguide ($P_f < 70$ kW);
 - Real quench or field emission (rf gap voltage < 1.6 MV);
 - Vacuum burst due to hydrogen desorption (vacuum better than 0.7 nTorr);




SRF trip due to mismatch of beam loaded cavity






SRF trip due to mismatch of beam loaded cavity - kicker misfired















Spontaneous kicker fired
(bad grounding contact)






SRF Trip due to mismatch of beam loaded cavity - SW6 fault



history-S1-51-deBug-Orbit-SMG.his




Feedback loop oscillations due to heavy beam loading






The beam trip caused by kicker misfired



Kicker #2 miss fire during Top-up Injection.








Trip caused by the SWLS main power supply failed

SWLS main coil PS failed

030 10/19/2006

17:52




10 Hz archived data, SWLS MPS drop lead beam current drop later slightly!




Trip caused by the SWLS main power supply failed - cont.

SWLS Trip Event on 19-Oct-2006 17:52;41



SWLS MPS tripped firstly (Vision XP data)。


Reason: SWLS main power supply failed – control firmware problem!





SW6 and IASW-R6 quench - I

SID Trip Event on 25-Sep-2007






SW6 and IASW-R6 quench - II (SW6 quench)

SID Trip Event on 25-Sep-2007 14:03:52









Partial beam loss





SW6 and IASW-R6 quench - III (SW6 quench)


SID Trip Event on 25-Sep-2007 14:03:52





SW6 and IASW-R6 quench - IV (IASW-R6 quench)

SID Trip Event on 25-Sep-2007 14:04:34







Time (sec)







SW6 and IASW-R6 quench - V (IASW-R6 quench)

SID Trip Event on 25-Sep-2007 14:04:34



Injection



Time (sec)



SW6 and IASW-R6 quench - VI

- 25-Sep-2007 14:03:51 SW6 quench.
 - * SW6 quench happened.
 - * MPS output dropped to 0 (before PLC interlock tripped MPS).

- 25-Sep-2007 14:04:34 IASW-R6 quench.
 - * Partial beam loss happened during injection instance.
 - * IASW-R6 quench.
 - * PLC interlock tripped MPS.


- Unknown reason caused SW6 quench, then partial beam loss at every injection instance, then IASW-R6 quench.

- Many improvements were done: coil winding (**poster WEPC114**), liquid He filling procedure, interlock logic modification...




Beam loss induced IASW-R6 trip (2008/04/15 06:57)


Summary




SWLS



SW6




IASW-R6



Reason: one vertical corrector PS failed


Kicker diagnostic (VME digitizer working in segmented capture mode)

Maintenance test



Beam Loss

Normal top-up injection





BPM post-mortem data for large kicker jitters

Libera Brilliance post-mortem data (turn-by-turn)




Diagnostics node (10 KHz rate for ~ 10 sec) is in implementation

Short-time
Fourier Analysis

Spectrogram



K1 trigger -150ns

R1BPM3




Beam Loss

SRF Interlock Sum Active






BPM post-mortem data for IASW-R6 trip



Vertical tune jumps due to
IASW-R6 trip





What we have achieved?

- Several different tools are available.
- Some occasions have helped to identify some peculiar events.
- However no all events can explanation.
=> further efforts are essential !
- Simple automatic signal analysis are supported.

Our current efforts

- Better integration of various diagnostic tools with the control system.
- Archive the events.
- **Develop automatic analysis tools to search various signals.**
- **Develop better user interface.**
- Automatic report generation.



Summary

- Taiwan Light Source (TLS) is current operated at 301 mA top-up operation. Top-up operation at 360 mA was commissioning.
=> **Poster WEPC043**
(stable beam up to 400 mA has been tested)
- Photon flux constancy can be kept around $\sim 0.05\%$.
- Availability is achieved 97 ~ 99% routinely.
- To provide user better service, reduce trip rate is an important routine job.
- Improving reliability, availability and serviceability is still on going.
- All of the experiences will help the reliability and availability design for the newly proposed Taiwan Photon Source.

=> Reliability design for various subsystem.

=> Post-mortem buffer are expected embedded in BPM electronics, superconducting insertion devices' controller, LLRF system, power supply controller, FOFB diagnostic node, ... etc.



We learn and get helps from accelerator
community a lot.

Thank You

Hope we can contribute something!

Thank You for Your Attention!